



**ACE INSPECTORS**  
 Tx License 8796  
 208 Montego Bay  
 El Paso, Tx 79912  
 Tel (915) 539 - 7193  
 Fax (915) 585 - 7195

Draw Inspection Date: 20 March 2006

Inspector's Name: Morgan Benson  
 Tx License 8796

Construction Company:	
Name:	Davin Builders
Contact:	Nicole Daniel
Phone:	(915) 406 - 1983
Fax:	

Lending Institution:	
Name:	Alamo Canyon Bank
Contact:	Marie Rey
Phone:	(915) 320 - 1985
Fax:	

Construction Site				
Address	City	Lot	Block	Sub - Division
1020 Naomi Road	El Paso	01	03	Miners Hill



#	Draw Inspection Item	% Standard	% Complete
1	Earth Graded & Leveled	2	2
2	Forms Constructed	3	3
3	Plumbing Buried in Trenches	2	2
4	Pads Poured	5	5
5	Rock walls, Fencing Constructed	3	
6	Framing Constructed	9	9
7	Sheathing, Siding Applied	4	4
8	Roof Decked	3	3
9	Windows Installed	2	2
10	Plumbing branches Installed	2	2
11	Roof Covering Applied	4	
12	Electrical branches Installed	3	1.5
13	HVAC Ducting Installed	3	1.5
14	Insulation Installed	2	0.5
15	Sheetrock Installed	4	
16	Sheetrock Finished	3	
17	Masonry, Stucco Applied	7	
18	Front/Back/Garage Doors Installed	2	
19	Kitchen Cabinets / Bath Vanities	3	
20	Interior Doors, Trim Installed	3	
21	Interior Painted	4	
22	Exterior Painted	4	
23	Flooring Finished	3	
24	Kitchen Counter Tops Installed	2	
25	Bath Enclosures & Tops Installed	2	
26	Hardware, Mirrors Installed	1	
27	Wall Covering Installed	1	
28	Appliances Installed	2	
29	Driveway, Patio, Walks Finished	2	
30	Electrical Fixtures Installed	2	
31	Plumbing Fixtures Installed	2	
32	Carpet Installed	2	
33	HVAC, WH Units Installed	2	
34	Yards Landscaped	1	
35	Gutters, Exterior Fixtures Installed	1	
<b>Total</b>		100	35.50